



1: 2018_01 Zugang zum Südturm



2: 2018_02 sichtbare Holzkonstruktion zeigt keinerlei Schäden



3: 2019_01_IMG_2606_Turmhaube Aufnahme mit Drohne



4: 2019_02_IMG_2726_Stiel Kugel



5: 20200713-WA0001



6: 20200713-WA0002



7: 20200713-WA0003



8: 20200713-WA0004



9: 20200713-WA0005



10: 20200713-WA0006



11: 20200713-WA0007



12: 20200713-WA0008



13: 20200714-WA0005



14: 20200714-WA0006



15: 20200714-WA0007



16: 20200714-WA0008



17: 20200714-WA0009



18: 20200714-WA0010



19: 20200714-WA0011



20: 20200714-WA0012



21: 20200714-WA0017




22: 20200714-WA0018



23: 20200714-WA0019



24: 20200714-WA0020



25: 20200714-WA0021



26: 20200714-WA0022



27: 20200722-IMGP0123



28: 20200722-IMGP0124



29: 20200722-IMGP0125



30: 20200722-IMGP0126



31: 20200722-IMGP0127



32: 20200722-IMGP0128



33: 20200722-IMGP0129



34: 20200722-IMGP0130



35: 20200722-IMGP0131



36: 20200722-IMGP0132



37: 20200722-IMGP0133



38: 20200722-IMGP0134



39: 20200722-IMGP0135



40: 20200722-IMGP0136



41: 20200722-IMGP0137



42: 20200723-WA0000



43: 20200723-WA0001



44: 20200723-WA0002



45: 20200723-WA0003



46: 20200723-WA0004



47: 20200723-WA0005



48: 20200723-WA0006



49: 20200723-WA0007



50: 20200723-WA0008



51: 20200723-WA0009



52: 20200806_IMGP0269



53: 20200806_IMGP0270



54: 20200806_IMG0271



55: 20200806_IMG0272



56: 20200806_IMG0273



57: 20200806_IMG0274



58: 20200806_IMGP0275



59: 20200806_IMGP0276



60: 20200806_IMG0277



61: 20200806_IMG0278



62: 20200831-WA0000



63: 20200831-WA0000-1



64: 20200831-WA0001



65: 20200831-WA0002



66: 20200831-WA0003



67: 20200831-WA0004



68: 20200831-WA0005



69: 20200831-WA0006



70: 20201013_IMGP0561



71: 20201013_IMGP0562



72: 20201106-IMGP0863



73: 20201106-IMGP0864_Zwischendecke Turm



74: 20201106-IMGP0865



75: 20201106-IMGP0872



76: 20201106-IMGP0873



77: 20201106-IMG0874



78: 20201106-IMGP0875



79: 20201106-IMGP0876



80: 20201106-IMG0877_Decke Haube



81: 20201106-IMGP0878_Sparren Turmhaube



82: 20201209-IMGP0927



83: 20201209-IMGP0928



84: 20201209-IMGP0929



85: 20201209-IMGP0930



86: 20201209-IMGP0931



87: 20201209-IMGP0932



88: 20201209-IMGP0933



89: 20201209-IMGP0934



90: 20201209-IMGP0935_Decke Turmhaube



91: 20201215-IMGP0976



92: 20201215-IMGP0977_Holzfraß Stütze



93: 20201215-IMGP0978



94: 20201215-IMG0979_Holzgesims



95: 20201215-IMGP0980



96: 20201215-IMGP0981Holz Turm



97: 20210302_IMG1170_Laterne



98: 20210302_IMGP1171_Holz



99: 20210401_IMGP1318



100: 20210401_IMGP1319



101: 20210401_IMGP1320_Schalung



102: 20210401_IMGP1321



103: 20210401_IMGP1322



104: 20210401_IMGP1323_Haube Schäden



105: 20210401_IMGP1324



106: 20210511_DSC_0243



107: 20210511_DSC_0244



108: 20210615-WA0001 (1)



109: 20210615-WA0001



110: 20210615-WA0002



111: 20210707-WA0000




112: 20210707-WA0001



113: 20210707-WA0002



114: 20210707-WA0003



115: 20210707-WA0004



116: 20210729-WA0000



117: 20210729-WA0001



118: 20210729-WA0002



119: 20210729-WA0003



120: 20210810_IMGP2148