

Deutsches Landwirtschaftsmuseum – Schloss Blankenhain

Sanierung Türme nach Sturmschaden - Nordturm



1: IMG_6820



2: IMG_6821



3: IMG_6824



4: IMG_6825



5: IMG_6826



6: IMG_6827



7: IMG_6828



9: IMG_6830



10: IMG_6831



11: IMG_6832



12: IMG_6936



13: IMG_6938



14: IMG_6939

16: IMG_6941



17: IMG_6942



18: IMG_6943



19: IMG_6953



20: IMG_6954



21: IMG_6955



22: IMG_6956



23: IMG_6957



24: IMG_6958



25: IMG_6959



26: IMG_6960



27: IMG_6961



28: IMG_6962



29: IMG_6963



30: IMG_6964